WELDING TECHNOLOGY, ASSOCIATE OF APPLIED SCIENCE

Admission

No admission requirements.

Job entry requirements:

- Pass a drug test on a regular basis;
- Pass a criminal background check;[1]
- Some career paths require a TWIC Card; and
- Some career paths require a good driving record.

[1] Requirements vary based on type of offense and years since the offense, or the requirements of the facility where the work is being performed.